

BD-R/RE Compatibility Drives Status_17.01.2010

Disc Type	Drives Name	Drives Model	Firmware	*Drive Max Writing	Writing Speed	Reading Speed	Problem observed
BD-R2X Compatibility Details	HL-DT-STBD-RE (LG)	GGW-H20L	YL05	6x	2x	4x	
	HL-DT-STBD-RE (LG)	GBW-H10N	GL06	4x	4x	4x	
	HL-DT-STBD-RE (LG)	BH08NS20	EL02	8x	6x	8x	
	HL-DT-STBD-RE (LG)	BH10NS30	EL00	10x	2x	10x	
	ATAPI BD B (Lite-On)	DH4B1S	7P5B	4x	4x/2x	4x/2x	Sometimes speed is 2x
	PLEXTOR BD-R	PX-B920SA	1.03	4x	4x	4x	
	MATSHITABD (Panasonic)	MLT LF-PB271	1.00	4x	2x	2x	
	MATSHITABD (Panasonic)	MLT LF-PB371	1.02	6x	2x	2x	
	MATSHITABD (Panasonic)	MLT SW-5583	1032	4x	2x	2x	
	**MATSHITABD- (Panasonic)	MLT SW-5584	1.00	8x	2x	2x	
	PIONEER BD-RW	BDR-202	1.07	5x	4x	4x	
	PIONEER BD-RW	BDR-205	1.03	10x	2x	8x	
	SONY BDRW	BWU-200S	1.0b	4x	2x	2x	
	SONY BDRW	BWU-300S	1.0b	6x	2x	2x	
BD-R4X Compatibility Details	HL-DT-STBD-RE (LG)	GGW-H20L	YL05	6x	6x/2x	6x/2x	Sometime speed is 2x
	HL-DT-STBD-RE (LG)	GBW-H10N	GL06	4x	4x	4x	
	HL-DT-STBD-RE (LG)	BH08NS20	EL02	8x	8x	8x	
	HL-DT-STBD-RE (LG)	BH10NS30	EL00	10x	8x	10x	
	ATAPI BD B (Lite-On)	DH4B1S	7P5B	4x	4x	4x	
	PLEXTOR BD-R	PX-B920SA	1.03	4x	4x	4x	
	MATSHITABD (Panasonic)	MLT LF-PB271	1.00	4x	4x/2x	4x	Sometimes writing speed is 2x
	MATSHITABD (Panasonic)	MLT LF-PB371	1.02	6x	4x	4x	
	MATSHITABD (Panasonic)	MLT SW-5583	1032	4x	4x	4x	
	**MATSHITABD- (Panasonic)	MLT SW-5584	1.00	8x	4x	4x	
	PIONEER BD-RW	BDR-202	1.07	5x	4x	4x	
	PIONEER BD-RW	BDR-205	1.03	10x	10x	8x	
	SONY BDRW	BWU-200S	1.0b	4x	4x	4x	
	SONY BDRW	BWU-300S	1.0b	6x	4x	4x	
BD-R6X Compatibility Details	HL-DT-STBD-RE (LG)	GGW-H20L	YL05	6x			Not supported
	HL-DT-STBD-RE (LG)	GBW-H10N	GL06	4x	4x	4x	
	HL-DT-STBD-RE (LG)	BH08NS20	EL02	8x	8x	8x	
	HL-DT-STBD-RE (LG)	BH10NS30	EL00	10x	10x	10x	
	ATAPI BD B (Lite-On)	DH4B1S	7P5B	4x	4x	4x	
	PLEXTOR BD-R	PX-B920SA	1.03	4x	4x	4x	
	MATSHITABD (Panasonic)	MLT LF-PB271	1.00	4x	4x	4x	Sometimes W. speed is 2x
	MATSHITABD (Panasonic)	MLT LF-PB371	1.02	6x	6x	8x	
	MATSHITABD (Panasonic)	MLT SW-5583	1032	4x	4x	4x	
	**MATSHITABD- (Panasonic)	MLT SW-5584	1.00	6x	6x	6x	
	PIONEER BD-RW	BDR-202	1.07	5x			Not supported
	PIONEER BD-RW	BDR-205	1.03	8x	2x	8x	
	SONY BDRW	BWU-200S	1.0b	4x	4x	4x	
	SONY BDRW	BWU-300S	1.0b	6x	6x	8x	
BD-RE2X Compatibility Details	HL-DT-STBD-RE (LG)	GGW-H20L	YL05	2x	2x	2x	
	HL-DT-STBD-RE (LG)	GBW-H10N	GL06	2x	2x	2x	
	HL-DT-STBD-RE (LG)	BH08NS20	EL02	2x	2x	2x	
	HL-DT-STBD-RE (LG)	BH10NS30	EL00	2x	2x	6x	
	ATAPI BD B (Lite-On)	DH4B1S	7P5B	2x	2x	2x	
	PLEXTOR BD-R	PX-B920SA	1.03	2x	2x	2x	
	MATSHITABD (Panasonic)	MLT LF-PB271	1.00	2x	2x	2x	
	MATSHITABD (Panasonic)	MLT LF-PB371	1.02	2x	2x	2x	
	MATSHITABD (Panasonic)	MLT SW-5583	1032	2x	2x	2x	
	**MATSHITABD- (Panasonic)	MLT SW-5584	1.00	2x	2x	2x	
	PIONEER BD-RW	BDR-202	1.07	5x	2x	2x	
	PIONEER BD-RW	BDR-205	1.03	2x	2x	2x	
	SONY BDRW	BWU-200S	1.0b	2x	2x	2x	
	SONY BDRW	BWU-300S	1.0b	2x	2x	2x	

Updated drives are in **BOLD** font